



KUBA PTY. PTY LTD/AS

IWR LIFTING

A.B.N. 18 060 137 475 A.C.N. 060 137 475
12 Harris Street, Port Kembla N.S.W.
PO Box 4, PORT KEMBLA N.S.W. 2505

Phone: (02) 4274 4668

Website: www.iwrlifting.com.au

Email: info@iwrlifting.com.au

LIFTING GEAR INSPECTIONS REPORT

COMPANY NAME

ADDRESS

CURRENT TAG COLOUR

INSPECTED BY



SERIAL NUMBER	INSPECTION REFERENCE STANDARD	DESCRIPTION	LOCATION	RESULTS ON INSPECTION DATES			FREQ MONTHS	NEXT DUE DATE
				10/03/2019	15/03/2020			
1964	AS 3775	Chain set 2 leg x 8mm x 4 metre	Y G D 91 J				12	15/03/2021
23956	AS 3775	Chain set 2 leg x 8mm x 6 metre	Y G D 91 J				12	15/03/2021
23957	AS 3775	Chain set 2 leg x 8mm x 6 metre	Y G D 91 J				12	15/03/2021

This inspection report has been prepared and issued to you in good faith. You are responsible to ensure that before use:-

- * Lifting gear is in good condition.
- * Rated capacity is not exceeded.
- * Competent personnel are engaged.

