

KUBA PTY, PTY LT D T/AS

## WR LIFTING

A.B.N. 18 060 137 475 A.C.N. 060 137 475 12 Harris Street, Port Kembla N.S.W. PO Box 4, PORT KEMBLA N.S.W. 2505 Phone: (02) 4274 4668

Website: www.iwrlitting.com.au E-mail:info@wrlitting.com.au

## LIFTING GEAR INSPECTIONS REPORT

COMPANY NAME	CAPITAL CRANES - 20TON FRANNA	INSPECT	ED BY	R. V	an Hees	
	SHEPPARD STREET HUME 2620 CAPITALCRANES@BIGPOND.COM					
CURRENT TAG		COMPLIES	NO COMPL		NOT FOUND	
COLOUR						Ī

SERIAL NUMBER	INSPECTION REFERENCE STANDARD	DESCRIPTION	LOCATION	RESULTS ON INSPECTION DATES	FREQ MONTHS	NEXT S DUE DATE
1755	AS 3775	Chain set 2 leg x 10mm x 3 metre	20 T Franna	10/03/2019 15/03/2020	12	15/03/2021
241	AS 3775	Chain set 2 leg x 10mm x 6 metre	20 T Franna	10/03/2019 15/03/2020	12	15/03/2021
248	AS 3775	Chain set 2 leg x 10mm x 6 metre	20 T Franna	10/03/2019 15/03/2020	12	15/03/2021
0251	AS 3775	Chain set 2 leg x 13mm x 6 metre G100	20 T Franna	10/03/2019 15/03/2020	12	15/03/2021
0252	AS 3775	Chain set 2 leg x 13mm x 6 metre G100	20 T Franna	10/03/2019 15/03/2020	12	15/03/2021
1	AS 3775	Container lug SWL 12.5 ton	20 T Franna	10/03/2019 15/03/2020	12	15/03/2021
2	AS 3775	Container lug SWL 12.5 ton	20 T Franna	10/03/2019 15/03/2020	12	15/03/2021
3	AS 3775	Container lug SWL 12.5 ton	20 T Franna	10/03/2019 15/03/2020	12	15/03/2021
4	AS 3775	Container lug SWL 12.5 ton	20 T Franna	10/03/2019 15/03/2020	12	15/03/2021
02913	Visual Inspection	Franna Swivel hook 20 ton	20 T Franna	10/03/2019 15/03/2020	12	15/03/2021
1200836	AS 4991-2005	Spreader Beam	20 T Franna	10/03/2019 15/03/2020	12	15/03/2021

This inspection report has been prepared and issued to you in good faith. You are responsible to ensure that before use:-

- \* Lifting gear is in good condition.
- \* Rated capacity is not exceeded.
- \* Competent personnel are engaged.