



KUBA PTY. PTY LTD/AS

IWR LIFTING

A.B.N. 18 060 137 475 A.C.N. 060 137 475
12 Harris Street, Port Kembla N.S.W.
PO Box 4, PORT KEMBLA N.S.W. 2505

Phone: (02) 4274 4688

Website: www.iwrlifting.com.auEmail: info@iwrlifting.com.au

LIFTING GEAR INSPECTIONS REPORT

COMPANY NAME CAPITAL CRANES - 25T FRANNA 2013

INSPECTED BY R. Van Hees

ADDRESS SHEPPARD STREET HUME 2620
CAPITALCRANES@BIGPOND.COMCURRENT TAG
COLOUR

COMPLIES NON COMPLIANT NOT FOUND



SERIAL NUMBER	INSPECTION REFERENCE STANDARD	DESCRIPTION	LOCATION	RESULTS ON INSPECTION DATES				FREQ MONTHS	NEXT DUE DATE
				10/03/2019	15/03/2020				
1715	AS 3775	Chain set 1 leg x 10mm x 1/2 metre	25 T Franna 2013	10/03/2019	15/03/2020			12	15/03/2021
001	AS 3775	Chain set 2 leg x 10mm x 3 metre	25 T Franna 2013	10/03/2019	15/03/2020			12	15/03/2021
0246	AS 3775	Chain set 2 leg x 10mm x 6 metre	25 T Franna 2013	10/03/2019	15/03/2020			12	15/03/2021
0238	AS 3775	Chain set 2 leg x 10mm x 8 metre	25 T Franna 2013	10/03/2019	15/03/2020			12	15/03/2021
2695	AS 3775	Chain set 2 leg x 13mm x 5 metre G100	25 T Franna 2013	10/03/2019	15/03/2020			12	15/03/2021
2696	AS 3775	Chain set 2 leg x 13mm x 5 metre G100	25 T Franna 2013	10/03/2019	15/03/2020			12	15/03/2021
7	AS 3775	Container lug SWL 12.5 ton	25 T Franna 2013	10/03/2019	15/03/2020			12	15/03/2021
5	AS 3775	Container lug SWL 12.5 ton	25 T Franna 2013	10/03/2019	15/03/2020			12	15/03/2021
6	AS 3775	Container lug SWL 12.5 ton	25 T Franna 2013	10/03/2019	15/03/2020			12	15/03/2021
8	AS 3775	Container lug SWL 12.5 ton	25 T Franna 2013	10/03/2019	15/03/2020			12	15/03/2021
14468	Visual Inspection	Franna Hook 25 ton	25 T Franna 2013	10/03/2019	15/03/2020			12	15/03/2021
14469	Visual Inspection	Franna Hook 9 ton	25 T Franna 2013	10/03/2019	15/03/2020			12	15/03/2021
1502766	AS 4991-2005	Franna Lifting beam	25 T Franna 2013	10/03/2019	15/03/2020			12	15/03/2021
0017	AS 1353.2	Round Sling 3 000 kg x 3 metre	25 T Franna 2013	1/04/2019	15/03/2020			12	15/03/2021
0019	AS 1353.2	Round Sling 3 000 kg x 3 metre	25 T Franna 2013	1/04/2019	15/03/2020			12	15/03/2021

This inspection report has been prepared and issued to you in good faith. You are responsible to ensure that before use:-

- * Lifting gear is in good condition.
- * Rated capacity is not exceeded.
- * Competent personnel are engaged.

COMPLIES NON COMPLIANT NOT FOUND

