



KUBA PTY. PTY LTD/AS

**IWR LIFTING**A.B.N. 18 060 137 475 A.C.N. 060 137 475  
12 Harris Street, Port Kembla N.S.W.  
PO Box 4, PORT KEMBLA N.S.W. 2505

Phone: (02) 4274 4668

Website: [www.iwrlifting.com.au](http://www.iwrlifting.com.au)Email: [info@iwrlifting.com.au](mailto:info@iwrlifting.com.au)**LIFTING GEAR INSPECTIONS REPORT**

COMPANY NAME CAPITAL CRANES - 60T LIEBHERR UNIT 2

INSPECTED BY R. Van Hees

ADDRESS SHEPPARD STREET HUME 2620  
CAPITALCRANES@BIGPOND.COMCURRENT TAG  
COLOUR

COMPLIES NON COMPLIANT NOT FOUND



SERIAL NUMBER	INSPECTION REFERENCE STANDARD	DESCRIPTION	LOCATION	RESULTS ON INSPECTION DATES				FREQ MONTHS	NEXT DUE DATE
24086-1	AS 3775	Chain set 2 leg x 10mm x 6 metre	60 T Liebherr Unit 2	10/03/2019	15/03/2020			12	15/03/2021
24086-2	AS 3775	Chain set 2 leg x 10mm x 6 metre	60 T Liebherr Unit 2	10/03/2019	15/03/2020			12	15/03/2021
24086-3	AS 3775	Chain set 2 leg x 10mm x 6 metre	60 T Liebherr Unit 2	10/03/2019	15/03/2020			12	15/03/2021
12804-1	AS 3775	Chain set 2 leg x 13mm x 6 metre G100	60 T Liebherr Unit 2	10/03/2019	15/03/2020			12	15/03/2021
12804-2	AS 3775	Chain set 2 leg x 13mm x 6 metre G100	60 T Liebherr Unit 2	10/03/2019	15/03/2020			12	15/03/2021
24085-1	AS 3775	Container Lifting Lug	60 T Liebherr Unit 2	10/03/2019	15/03/2020			12	15/03/2021
24085-2	AS 3775	Container Lifting Lug	60 T Liebherr Unit 2	10/03/2019	15/03/2020			12	15/03/2021
24085-3	AS 3775	Container Lifting Lug	60 T Liebherr Unit 2	10/03/2019	15/03/2020			12	15/03/2021
24085-4	AS 3775	Container Lifting Lug	60 T Liebherr Unit 2	10/03/2019	15/03/2020			12	15/03/2021
1171	AS 166-1-1995	Counterweight Lifting Sling	60 T Liebherr Unit 2		15/03/2020			12	15/03/2021
1181	AS 166-1-1995	Counterweight Lifting Sling	60 T Liebherr Unit 2		15/03/2020			12	15/03/2021
1502754	AS 4991-2005	Franna Lifting Beam	60 T Liebherr Unit 2	10/03/2019	15/03/2020			12	15/03/2021
0105	AS 1353.2	Round Sling 3 000 kg x 3 metre	60 T Liebherr Unit 2	24/06/2019	15/03/2020			12	15/03/2021
0109	AS 1353.2	Round Sling 3 000 kg x 3 metre	60 T Liebherr Unit 2	24/06/2019	15/03/2020			12	15/03/2021
0111	AS 1353.2	Round Sling 3 000 kg x 3 metre	60 T Liebherr Unit 2	24/06/2019	15/03/2020			12	15/03/2021
0113	AS 1353.2	Round Sling 3 000 kg x 3 metre	60 T Liebherr Unit 2	24/06/2019	15/03/2020			12	15/03/2021
0059	AS 1353.2	Round Sling 3 000 kg x 6 metre	60 T Liebherr Unit 2	24/06/2019	15/03/2020			12	15/03/2021
0074	AS 1353.2	Round Sling 3 000 kg x 6 metre	60 T Liebherr Unit 2	24/06/2019	15/03/2020			12	15/03/2021

This inspection report has been prepared and issued to you in good faith. You are responsible to ensure that before use:-

- \* Lifting gear is in good condition.
- \* Rated capacity is not exceeded.
- \* Competent personnel are engaged.

COMPLIES NON COMPLIANT NOT FOUND

