



KUBA PTY. PTY LTD/AS

IWR LIFTINGA.B.N. 18 060 137 475 A.C.N. 060 137 475
12 Harris Street, Port Kembla N.S.W.
PO Box 4, PORT KEMBLA N.S.W. 2505

Phone: (02) 4274 4668

Website: www.iwrlifting.com.auEmail: info@iwrlifting.com.au**LIFTING GEAR INSPECTIONS REPORT**

COMPANY NAME CAPITAL CRANES - 95 TON LIEBHERR

INSPECTED BY R. Van Hees

ADDRESS SHEPPARD STREET HUME 2620
CAPITALCRANES@BIGPOND.COMCURRENT TAG
COLOUR

COMPLIES NON COMPLIANT NOT FOUND



SERIAL NUMBER	INSPECTION REFERENCE STANDARD	DESCRIPTION	LOCATION	RESULTS ON INSPECTION DATES				FREQ MONTHS	NEXT DUE DATE
1709	AS 3775	Chain set 2 leg x 10mm x 7 metre	95 T Liebherr	10/03/2019	15/03/2020			12	15/03/2021
1710	AS 3775	Chain set 2 leg x 10mm x 7 metre	95 T Liebherr	10/03/2019	15/03/2020			12	15/03/2021
12144-1	AS 3775	Chain set 2 leg x 13mm x 6 metre G100	95 T Liebherr	10/03/2019	15/03/2020			12	15/03/2021
12144-2	AS 3775	Chain set 2 leg x 13mm x 6 metre G100	95 T Liebherr	10/03/2019	15/03/2020			12	15/03/2021
13	AS 3775	Container lifting lug SWL 12.5 ton	95 T Liebherr	10/03/2019	15/03/2020			12	15/03/2021
14	AS 3775	Container lifting lug SWL 12.5 ton	95 T Liebherr	10/03/2019	15/03/2020			12	15/03/2021
15	AS 3775	Container lifting lug SWL 12.5 ton	95 T Liebherr	10/03/2019	15/03/2020			12	15/03/2021
16	AS 3775	Container lifting lug SWL 12.5 ton	95 T Liebherr	10/03/2019	15/03/2020			12	15/03/2021
25213-1	AS 1666.1-1995	Counterweight Slings 9.6 ton	95 T Liebherr	10/03/2019	15/03/2020			12	15/03/2021
25213-2	AS 1666.1-1995	Counterweight Slings 9.6 ton	95 T Liebherr	10/03/2019	15/03/2020			12	15/03/2021
150067	AS 4991-2005	Franna Lifting Beam	95 T Liebherr	10/03/2019	15/03/2020			12	15/03/2021
1719	AS 3775	Ring 12.5 ton	95 T Liebherr	10/03/2019	15/03/2020			12	15/03/2021

This inspection report has been prepared and issued to you in good faith. You are responsible to ensure that before use:-

- * Lifting gear is in good condition.
- * Rated capacity is not exceeded.
- * Competent personnel are engaged.

COMPLIES NON COMPLIANT NOT FOUND

